

Illinois Commerce Commission**Pipeline Safety****Pipeline Safety Report****Inspection #: 2015-P-00348**

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Exit Meeting Contact: Kevin Glaspy	Total Man Days: 3
Pipeline Safety Representative(s): Donald Hankins	
Company Representative to Receive Report: Michael Fuller	Emailed Date:
Company Representative's Email Address: mfuller2@ameren.com	10/14/2015

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection - Field Audit	Lincoln	Donald Hankins	Lincoln	3	7/21/2015, 7/22/2015, 7/23/2015	Kevin Glaspy

Statement of Activities

On July 21, 22, & 23, 2015, Staff conducted a Field Audit of the Ameren Illinois Company's Lincoln inspection unit to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590. The audit included inspections of Ameren facilities including customer meters, cathodic protection, damage prevention, pressure limiting and regulating devices, valves and Odorization equipment

Exit Statement**INSPECTION FINDINGS****Standard Inspection - Field Audit****Issues(s) Found:**

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS**Issue(s) Corrected:**

[NO ISSUES CORRECTED]

Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

**Illinois Commerce Commission
Pipeline Safety
Pipeline Safety Report**

Inspection #: 2015-P-00348

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]